2000 MR2 (RM760U)

DI7CP-01

PROBLEM SYMPTOMS TABLE

If a normal code is displayed during the DTC check but the problem still occurs, check the circuits for each problem symptom in the order given in the table below and proceed to the relevant troubleshooting page. **NOTICE:**

When replacing ABS ECU, sensor or etc., turn the IG switch OFF.

Symptom	Suspected Area	See page
ABS does not operate	Only when 1. to 4. are all normal and the problem is still occurring, replace the ABS ECU. 3. Check the DTC reconfirming that the normal code is output. 4. IG power source circuit 5. Speed sensor circuit 6. Check the ABS actuator with a checker or TOYOTA hand—heldtester. If abnormal, check the hydraulic circuit for leakage	DI-154 DI-183 DI-163 BR-42
ABS does not operate efficiently	(See page DI–199). Only when 1. to 4. are all normal and the problem is still occurring, replace the ABS ECU. 1. Check the DTC reconfirming that the normal code is output. 2. Speed sensor circuit 3. Stop light switch circuit 4. Check the ABS actuator with a checker or TOYOTA hand—held tester. If abnormal, check the hydraulic circuit for leakage (See page DI–199).	DI-154 DI-163 DI-186 BR-42
ABS warning light abnormal	ABS warning light circuit ABS ECU	DI-192
DTC check cannot be done	Only when 1. and 2. are all normal and the problem is still occurring, replace the ABS ECU. 1. ABS warning light circuit 2. Tc terminal circuit	DI-192 DI-195
Speed sensor signal check cannot be done	 Ts terminal circuit ABS ECU 	DI-197

Author: Date: 326