DI7D9-01

DTC B2797/99 Communication Malfunction No. 1

CIRCUIT DESCRIPTION

This code is detected when an error occurs despite of normal communication.

(Example: Some noise is included in communication line.)


DTC No.	DTC Detection Condition	Trouble Area
B2797/99	Communicationerror	Wire harness Transponder key amplifier Unregistered key inserted before ECM

WIRING DIAGRAM

Refer to DTC B2796/99 on page DI-345.

INSPECTION PROCEDURE

1 Check noise.



PREPARATION:

Insert already registered master key in the key cylinder.

CHECK:

Using an oscilloscope or TOYOTA hand-held tester, check that noise is included in the CODE terminal of the ECM.

OK:

No noise is detected.

NG

Try to find cause of noise and remove it.

OK

2

Does it operate normally after replacement of transponder key amplifier?

Yes

Replace transponder key amplifier.

No

Check and replace ECM (See page IN-28).

2000 MR2 (RM760U)

Author: Date: 511