DIAGNOSTIC TROUBLE CODE CHART

DI1KH-05

DTC No. (See page)	Detection Item	Trouble Area
B2795 (DI-344)	Unmatched Key Code	Key Unregistered key inserted before
B2796 (DI-345)	No Communication in Immobiliser System	Key Transponder key amplifier Wire harness ECM
B2797 (DI-347)	Communication Malfunction No. 1	Wire harness Transponder key amplifier Unregistered key inserted before ECM
B2798 (DI-348)	Communication Malfunction No. 2	Key Transponder key amplifier Wire harness ECM

HINT:

To reduce the unnecessary exchange of ECM, check that a trouble occurs with the original ECM at the time of exchanging ECM and the problem will be solved with a new ECM.

Author: Date: 504

2000 MR2 (RM760U)