RS0KT-02

INSPECTION

HINT:

The SRS wire harness is integrated with the instrument panel wire harness assembly. All the connectors in the system are a standard yellow color.

VEHICLES NOT INVOLVED IN COLLISION 1.

Check a diagnostic system (See page DI-237).

2. **VEHICLES INVOLVED IN COLLISION**

- Check a diagnostic system (See page DI-237). (a)
- Check the breakage in all wires of the SRS wire harness, and exposed conductors. (b)
- Check to see if the SRS wire harness connectors are cracked or chipped. (c)

1093

Author:

Date:

2000 MR2 (RM760U)